

ERT - Simulacro / ERT - Drill: Run on 16/07/2022

This document was created in MY Compliance Management on 20/09/2022 14:40:50

Audit Details	
Audit name:	ERT - Simulacro / ERT - Drill
Audit date:	16/07/2022
Auditor:	David Pinto
Audit details:	Simulacro en áreas de trabajo / Work Area Drill
Overall Outcome:	Completed
Emergencia / Emergency	Incendio o explosion / Fire or explosion
Breve descripción del evento / Brief Event Description	15 julio 2022, Drill Primary Crusher 311 CV2001 Conato de Incendio en area de Bandas de transporte de material.
Especificar ubicación / Specify Location	Trituradora Primaria 311 CV2001
Hora de inicio / Starting Time	14:09
Hora de finalización / Ending Time	14:35
Departamento / Department	PP OPS - Primary Crushing

Notes

15 junio 2022, Trituradora Primaria 311, CV 2001, aproximadamente 14:09 se produce emanación de humo proximo a la banda trasportadora.

Se ejecutó el simulacro siguiendo el protocolo de emergencias, se evaluó que el sitio que fuera seguro y estable antes de ingresar, se realizó la llamada a Centro de Control con deficiencia en la comunicación radial por desperfectos en una de las radios y se siguieron las indicaciones dictadas por Centro de Control, el personal de operaciones en sitio se puso a disposición del personal de rescate para asistir en las tareas. El simulacro se ejecutó sin interrupciones o contratiempos.

La vía principal estaba obstruida por una grúa en operación de shut down de la 311-CR-3001 (PC3) y por esta razón se debe coordinar la evaluación de posible ingreso de los equipos de emergencias por las vías alternas de la 311-CR-1001 (PC1) y 311-CR-3001 (PC3), derecha e izquierda en caso de tener otra obstrucción o interferencia en las vías.

15 June 2022, Primary Crusher 311, CV 2001, approximately 14:09 smoke is produced near the conveyor belt.

The drill was run following the emergency protocol, it was evaluated that the site was safe and stable before entering, the call was made to Control Center with deficiency in radio communication due to damage to one of the radios and the indications given by Control Center were followed, On-site operations personnel were made available to rescue personnel to assist with the tasks. The drill ran without interruptions or setbacks.

The main track was obstructed by a crane in operation shut down the 311-CR-3001 (PC3) and for this reason it is necessary to coordinate the evaluation of possible entry of emergency equipment by the alternating routes of the 311-CR-1001 (PC1) and 311-CR-3001 (PC3), right and left in case of other obstruction or interference in the tracks.

Response Summary		
Section	Completed	Not completed
Audit	1	0

ERT - Simulacro / ERT - Drill: Run on 16/07/2022

This document was created in MY Compliance Management on 20/09/2022 14:40:50

Audit Criteria

#	Criteria	Details	Response
1	Completed Drill	Responsible will determine the drill	Completed

Signatures

Capacity: supervisor

Name: David Pinto



Documents



equipo de apoyo



Despliegue de equipos



atencion de simulacro

DOC - Evaluacion de simulacro CV-2001 15072022.doc